

## SERVICE INFORMATION

Techn. Customer Service BMW Motorcycles R 50, R 60, München, June 68
VKT 20 Gi/wi/sa R 69 S, Group: Frame No. 1/68 (266) eng.

Re: Fuel tap

Lately there have occasionally been complaints that with the fuel tap open the fuel supply fails. This deficiency can occur when the longer piece of the two fuel feed pipes touches the tool kit. As remedy the longer fuel pipe should be shortened by 4 to 5 mm.

Very truly yours,
Bayerische Motoren Werke
Aktiengesellschaft
ppa. i.V.

Delleske

Scholz