



SERVICE INFORMATION

ust.Serv.-Techn.Office
KT ER/wi/ha

2-Cylinder Motorcycles
Group: Engine

Munich, 11-2-1965
No. 1/65 (216) en.

Re: Improved Sealing between Engine Housing and Cylinder Flange
on the Two-Cylinder-Models

Dear Sirs,

In order to improve the sealing, the cylinder flange seating surface has been provided with circular grooves 0.1 mm deep at a distance of 2 mm one from another.

Commencing with frame No. 636 100 (R 50)
626 401 (R 60)
658 929 (R 69 S)

the above improvement has been become standard feature.

The ordering numbers for cylinders remain unaltered.

The new cylinder flange gasket of soft aluminium,

Part No. 00 10 161,

is installed from the following chassis numbers onwards:

638 105 (R 50)
626 681 (R 60)
658 929 (R 69 S).

With friendly greetings
BAYERISCHE MOTOREN WERKE
Aktiengesellschaft

Heab Makowitzki

i.V. Schaab i.V. Makowitzki