



# SERVICE INFORMATION

Techn. Customer Service  
VKT 20 fm/wi-ba

BMW Motorcycles 1 & 2 cyl.  
Group: Transmission

München, March 1969  
No.1/69 (270) en.

Re: Coil pressure spring for kickstarter

Dear Sirs,

In order to avoid an occasional cloncking of the kickstarter dog plate that causes annoying noises particularly while the transmission oil is still cold, the wire gauge of the cylindrical coil-type pressure spring has been increased by 0.2 mm to 1.3 mm.

Ordering No. 23 51 1 056 116.

Service Information No. 2/66 (237) is herewith superseded.

Very truly yours,

BAYERISCHE MOTOREN WERKE  
Aktiengesellschaft

ppa.

i.V.

  
Delleske

  
Bennewitz

Kennntnis genommen — Pris connaissance — Noted — Tomado nota — Preso conoscenza

Ablage — Archives — File — Archivio

Betriebsleitung

Werkstatt

KD-Annahme

Gewährl.-Sachb.

E-Teildienst

Betriebsleitung

Werkstatt