

Service-Information



BMW MOTORRAD GMBH Service R-VK-10 TR-ST	Motorcycle R60/7-1978 Technic Wheels and Tires	Munich, Oct.77 36 02 75(1008R)
---	--	-----------------------------------

Supplement II

For U.S.A. and Canada only

Subject: Michelin Tires M38

Dear Dealer,

The above tire is released for the R60 Models only, because it only is available in the "S" design (slow speed).

On all R75 to R100RS, this tire is not released.

1978 R80/7 - R100RS have "H" design tires (high speed) as standard equipment.

Advise your customers accordingly, when tires are to be released. Please also refer to older bulletins with the same number above.

If Michelin tires are mounted, watch for the directional mark.

Mount the front tire against the direction or backward for better braking performance, as tests have proven.


Mount the rear tire as marked.

Yours truly,

BMW MOTORRAD GMBH
Munich

i.V.

i.V.


Gonzalez


Blank

Kenntnis genommen - Pris connaissance - Noted - Tomado nota - Preso conoscenza					Ablage - Archives - File - Archivio	
Betriebsleitung Direction Management Dirección Direzione	Werkstatt Atelier Workshop Taller Officina	KD-Annahme Réception clientèle Cust. reception Recepción clientela Recezione clienti	Gewährl.-Sachb. Inspecteur garantie Warranty inspector Inspector garantia Ispettore garanzia	Teiledienst Service pièces détachées Spare parts service Servicio de recambios Servizio ricambi	Betriebsleitung Direction Management Dirección Direzione	Werkstatt Atelier Workshop Taller Officina